



# TEST REPORT

Test Report # 18A-000460 Date of Report Issue: March 7, 2018  
Date of Sample Received: March 5, 2018 Pages: Page 1 of 5

## CLIENT INFORMATION:

Company: Taizhou Sonduo Commodity Co.,Ltd  
Address: No.7 Huimin Road, West Industrial Zone,  
Huangyan,Taizhou City, Zhejiang Province, China.



## SAMPLE INFORMATION:

Product Name: Plastic Shaker Cup  
Model/style No.: 5042066  
Main Material: PP  
Buyer: -  
Supplier: Taizhou Sonduo Commodity Co.,Ltd  
Country of Distribution: -  
Testing Period: 03/05/2018-03/07/2018

## OVERALL RESULT:

**PASS**

Refer to page 2 for test result summary and appropriate notes.

HANGZHOU ASIAINSPECTION  
TECHNOLOGY CO., LTD

Kevin Lee  
Technical Manager





# TEST REPORT

Test Report # 18A-000460 Date of Report Issue: March 7, 2018  
Date of Sample Received: March 5, 2018 Pages: Page 2 of 5

---

## TEST RESULTS SUMMARY:

At the request of the client, the following tests were conducted:

CONCLUSION	TEST(S) CONDUCTED
PASS	Client's requirement, Bisphenol A content





**DETAILED RESULTS:**

**Client's requirement, Bisphenol A content**

Test method: US EPA 3550C:2007 & US EPA 8270D:2014  
Analytical Method: Gas Chromatography-Mass Spectrometer

Sample No.:	1	-	-	-	-	<b>Client's limit (mg/kg)</b>
Test Item	Result (mg/kg)	Result (mg/kg)	Result (mg/kg)	Result (mg/kg)	Result (mg/kg)	
Bisphenol A (BPA)	ND	-	-	-	-	<b>Not Detected</b>
<b>Conclusion</b>	PASS	-	-	-	-	

*Note:*  
mg/kg=milligram per kilogram  
ND=Not Detected(Reporting limit = 0.1mg/kg)





**SPECIMEN DESCRIPTION:**

Specimen No.	Specimen Description	Location
1	Transparent plastic	Body of cup





**SAMPLE PHOTO:**



-End Report-

